

Figure 3.2-3 Water level in a well showing effects of dewatering the Emery Mine. Water levels during 1980 provided by Consolidation Coal Co.




Figure 3.2-4 Effects of periodic discharge of water from the SUFCo Mine on streamflow in Convulsion Canyon at gaging station 09331850 (site 98 in section 10.0).

**FILED**

OCT 11 1994

SECRETARY, BOARD OF  
OIL, GAS & MINING

3.0 COAL MINING--Continued  
3.2 Hydrologic Impacts Due To Mine  
Dewatering

EXHIBIT 12